

# Vibration Survey Report — CWRU OR021@6\_0

Analysis timestamp: 2026-07-22T23:01:34 UTC

---

## Executive Summary

The committed diagnosis for **CWRU OR021@6\_0** is a **bearing outer-race fault (BPFO)**, assessed with **high confidence**. The dominant spectral peak on the radial (y) axis sits at 107.53 Hz — within 0.21% of the computed BPFO of 107.3 Hz — and is flanked by  $\pm 1 \times$  shaft-frequency sidebands, forming a textbook outer-race fault signature. ISO 20816 severity is unrated — ISO severity requires velocity data: velocity was not measured in this reading, so no severity rating can be established. A broadband velocity measurement (mm/s RMS, 10–1000 Hz, per ISO 20816) is required to establish the severity rating — see **Severity & Coverage** and **Recommended Follow-up Measurements**.

---

## Machine Details

| Field                | Value                                                       |
|----------------------|-------------------------------------------------------------|
| Machine              | CWRU OR021@6_0                                              |
| Type                 | Motor                                                       |
| Location             | —                                                           |
| Sensor / MAC         | CWRU-OR021@6_0                                              |
| ISO group / support  | 2 / rigid                                                   |
| ISO threshold source | ISO 20816-3:2022 — Group 2, rigid support                   |
| Running speed        | 1,796.0 rpm (29.93 Hz shaft frequency)                      |
| Overall vibration    | Not assessable — velocity not measured                      |
| Bearing model        | Not specified                                               |
| Bearing geometry     | 9 balls, ball Ø 7.94 mm, pitch Ø 39.04 mm, contact angle 0° |

---

## Severity & Coverage

**What was assessed:** Fault detection from the spectral and envelope evidence. The bearing outer-race finding stands entirely on that spectral evidence and is unaffected by the absence of a velocity measurement.

**What was not assessed:** ISO 20816 severity is unrated — ISO severity requires velocity data. The severity rating that places a machine in a vibration band is a velocity judgement; because velocity was not measured in this reading, it cannot be established. A broadband velocity measurement (mm/s RMS, 10–1000 Hz, per ISO 20816) is required to establish the severity rating. See **Recommended Follow-up Measurements**.

---

## Data Quality

**Gate verdict: WARN.**

All structural checks passed. One check requires attention:

| Check              | Status      | Detail                                                                                |
|--------------------|-------------|---------------------------------------------------------------------------------------|
| units_plausibility | <b>WARN</b> | Velocity not measured<br>— ISO severity not assessable<br>(acceleration-only reading) |

All other applicable checks (configuring, msg\_type, acceleration\_data\_validity, machine\_running, msg\_type\_motion, startup\_transient, startup\_window, metadata\_completeness) returned **pass**. The data-quality warning does not invalidate the spectral fault detection; it is reflected as a  $-0.5$  confidence factor in the bearing RCA (see Diagnosis).

---

## Diagnosis

**Bearing outer-race fault (BPFO) — severity: unrated — ISO severity requires velocity data — confidence: high**

The analysis committed to a **bearing outer-race fault (BPFO)** at **high confidence**.

The BPFO for this bearing geometry was computed at **107.3 Hz** at the measured shaft speed of 1,796.0 rpm. The dominant peak on the radial y-axis was observed at **107.53 Hz** (rank 1, amplitude 0.383 g), a match of **0.21%** — well within the  $\pm 3\%$  acceptance window. The  $1\times$  shaft component appears as the rank-2 peak at 29.90 Hz (0.336 g). The rank-3 peak at 137.42 Hz corresponds to the upper sideband (BPFO +  $1\times$  shaft), and the lower sideband at 77.63 Hz was also identified, confirming shaft-rate modulation of the outer-race tone — a hallmark of a localised outer-race defect.

No BPFO harmonic ( $2\times$  BPFO = 214.6 Hz) was committed as present.

### Confidence factors:

| Factor                                          | Effect |
|-------------------------------------------------|--------|
| BPFO peak matched on a radial axis              | +1.0   |
| Bearing tone on the expected radial axis        | +0.5   |
| BPFO is the dominant (rank-1) peak on y         | +1.0   |
| Frequency match within 0.21% of computed BPFO   | +1.0   |
| $\pm 1\times$ shaft sidebands present (2 found) | +1.0   |
| Data-quality warnings present on this reading   | -0.5   |

The net evidence supports a **high** confidence classification.

### Evidence Table

| Finding                         | Axis | Computed (Hz) | Observed (Hz) | Match | 2 $\times$ harmonic | Sidebands (Hz) |
|---------------------------------|------|---------------|---------------|-------|---------------------|----------------|
| Bearing outer-race fault (BPFO) | y    | 107.3         | 107.53        | 0.21% | Not present         | 77.6, 137.4    |

### Computed bearing fault frequencies at 1,796.0 rpm (29.93 Hz):

| Frequency                              | Value (Hz) |
|----------------------------------------|------------|
| BPFO (Ball Pass Frequency, Outer Race) | 107.30     |
| BPFI (Ball Pass Frequency, Inner Race) | 162.10     |
| BSF (Ball Spin Frequency)              | 70.55      |
| FTF (Fundamental Train Frequency)      | 11.92      |

### Trend Summary

No historical data points are available for this machine. Trend regression and z-score anomaly detection could not be performed; this reading represents the first data point on record. Establishing a baseline history (minimum 30 readings per the machine configuration) will enable statistical anomaly detection and trend monitoring going forward.

## Also Considered

No differential (set-aside) candidates were raised during this analysis. The bearing outer-race fault was the sole candidate and was committed directly.

---

## Recommended Follow-up Measurements

1. **Velocity measurement per ISO 20816 (10–1000 Hz broadband, mm/s RMS)** (*Priority: **high***) — Establishes the ISO 20816-3 severity zone. Severity cannot be assessed from this reading — velocity was not measured (acceleration-only) or was outside a plausible range — while fault detection from the spectral/envelope evidence is unaffected. *Trigger: ISO severity not assessable — velocity not measured.*
- 

## Recommendations

1. **Plan bearing replacement** at the next available maintenance window. The outer-race fault signature is strong (rank-1 dominant peak, tight frequency match, confirmed shaft-rate sidebands) and high confidence has been committed.
  2. **Monitor closely** until replacement can be scheduled. Increase measurement frequency to track any amplitude growth in the BPFO peak and its sidebands.
  3. **Obtain a broadband velocity measurement** (mm/s RMS, 10–1000 Hz) at the next inspection to establish the ISO 20816-3 severity rating and prioritise the maintenance timeline accordingly.
- 

## Limitations & Confidence Notes

- **ISO 20816 severity is unrated** — ISO severity requires velocity data. This reading was acceleration-only; no velocity measurement was available to establish a severity band under ISO 20816-3 (Group 2, rigid support).
- **No trend history available.** Statistical z-score anomaly detection and trend regression require a streaming baseline; no prior history points exist for this machine. Findings rest solely on the single-reading spectral evidence.
- **Data-quality warning present.** The `units_plausibility` check returned WARN (acceleration-only reading). This is reflected as a  $-0.5$  deduction in the confidence scoring but does not invalidate the spectral fault detection.
- **No bearing model number on record.** Fault frequencies were computed from the raw geometry (9 balls, ball  $\varnothing$  7.94 mm, pitch  $\varnothing$  39.04

mm, contact angle  $0^\circ$ ); no manufacturer model string was available to cross-reference.

---

DRAFT – prepared by automated analysis, pending analyst review.